ApprovSE GRETElease 2000/06/30 : CIA-RDP78B04560A004900010002-3

PHOTOGRAPHIC INTERPRETATION REPORT





HUANG-PU NAVAL BASE KUANG-CHOU, CHINA

NPIC/R-238/65 JULY 1965

GROUP 1 EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION Approved For Release 2000/06/30 : CIA-RDP78B04560A004900010002-3

WARNING

.

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

Approved For Release 2000/06/30 : CIA-RDP78B04560A004900010002-3

NO FOREIGN DISSEM

NPIC/R-238/65

HUANG-PU NAVAL BASE, KUANG-CHOU, CHINA

INTRODUCTION

This report is one of a series describing Chinese Communist shipyards and ports as observed on aerial photography.

The Huang-pu Naval Base is located approximately 9 nautical miles east-southeast of Kuang-chou (Canton) on Huang-pu Tao (Island) facing the Chu Chiang (River).

DESCRIPTION

The Naval Base (Figure 2) extends along the northern edge of the island and is undergoing considerable renovation and expansion. A new marine railway, a building ramp and

a small steel plant are under construction along the eastern edge of the base. Approximately 33 buildings have been removed and 35 buildings constructed during the period of comparative coverag

25X1D

25X1D

A land reclamation area is located along the western edge of the yard, where the western faces of the hills have been squared off and a small retaining wall installed parallel to Numerous areas of open storage for building materials are in this area. graving dock has been abandoned and was not in use during the entire period of this report.




FIGURE 1. LOCATION OF HUANG-PU NAVAL BASE, KUANG-CHOU, CHINA.

- 1 -

25X1A

25X1A

Approved For Release 2000/06/30 : CIA-RDP78B04560A004900010002-3 SECRET

NO FOREIGN DISSEM

NPIC/R-238/65


marine railway with adjoining building/repair ways, 5 marginal wharves, 1 off shore wharf, 4 piers and 4 T-head piers. Handling facilities

consist of numerous mobile cranes utilized throughout the yard but no heavy, fixed cranes are observed.

	X1D			igure 2)			
Location	Identification (Size (ft) Configuration/	Status	Identification	Size (ft) Configuration/ Hatches	Status	
		Hatenes		Unoccupied	2	25X1D	
1	Unoccupied		25X1D	Barge Probable YP	100 x 20	.5/(1)	
7	Small craft Small craft (6)	40-80 LOA	11	Probable YP	70×20		
8	Small Clair (0)			Unoccupied			
10	Barge	50 x 10	{ }	Unoccupied	(1 with vessel)	2	25X1I
11	Unoccupied	170 v 25	Under con-	2 Ways partially covered	(I with vesser)	Repair	.07(11
12	Probable tanker	170 x 35	struction	Possible PTF	120 x 20	Repair	
25X1D	2.74	40-60 LOA	U/C	Possible MSC	120 % 20		
	Small craft (4)	90 x 20	Construction				
	Possible Tugs (2)		/ repair				
	Possible combat vessel	¹¹⁰ × ²⁰ 25 X1D	Construction/				
	Possible comean received	25X1L	repair	U/I naval vessel	195 x 30	Possible	
20	Possible		Possible repair	Possible Shanghai-class PTI	7	repair	
	1 Out of the control		Possible		120 x 30	Possible	
	Possible YP		repair	Possible U/I Patrol Craft	120 x 30	repair	
	1	05740			100 x 20	Possible	
	Floating shearlegs crane	25X1D	25X1D	U/I vessel		repair	
				Small Surface Craft (2)	60 x 10	Possible repair	
				Probable Castle-class PF			
	Possible ocean tug	185 x 40	Possible	Probable Castle class			
24	Possible ocean bug		repair	 			
	Possible YP (2)		Possible	11			
	1 0551010 22 (-/		repair Possible	11			
	Barge	140 x 30		11			
		25X1	Possible				
	Barge	05-2-82	repair	III and lo II/C			
			Repair	Possible ship cradle U/C			
33	Coastal vessel	135 x 25	Repair	US LST-1-class LST			
	Possible MSC Probable US 136 ft-class MSC	C	Repair	Possible LSM			
34	Probable 03 100 10 offi			II/I vessel	135 x 30		
				Probable floating crane	100.00		
36	Unoccupied			3 Coastal vessels (3)	100-80 110 x 30		
90				Barge	200 x 30	Unloadin	g
	, , , om (a)			Coastal vessel	180 x 30	Unloadin	g
38	Probable British LCT (3) -		Repair	Coastal vessel	90 x 20	Unloadin	g
	class LCU			Small craft (2)	60-100		
	Probable work barge	210 x 40	25X1D	Barges (3)			
47	Possible YP (2)						
	Small craft (4)	(Approx) 60	LOA	Barge	60 x 10	7/4 Offloadi	ng
48	US LSM-1-class LSM			Freighter	320 x 40/KFF	1/ + 011,0341	0
49	-			T-13-class MSF			
40		80 x 15		Floating shearlegs crane			
59	Barges (2)	00 X 10		Work barge			
	ar			Under construction Probable Kronshtadt-cla	ss PC	Repair	l a
60	Not constructed Coastal vessels	170 x 30	Off loading	Coastal vessel	100 x 20	Possibl	
67	Coastal vessels Coastal vessels (2)	95 x 15	Off loading	III.		repair Repair	
	Barges (7)	60 x 10	1 on quay	Possible Whampoa-class	YP 25X	1D Repair	
	Darges (1)			(2)		Repair	
				Swatow-class PGM		Repair	
				Possible YP			

SECRET

NPIC/R-238/65



SECRET NO FOREIGN DISSEM

NPIC/R-238/65

PHOTOGRAPHY

Classification
SECRET/No Foreign Dissem

SECRET/No Foreign Dissem

1

4

MAPS OR CHARTS

US Air Target Mosaic, Series 50, Sheet S0614, 3d ed. Feb 53 (SECRET/No Foreign Dissem)

DOCUMENTS

25X1D

25X1C

REQUIREMENT

25X1C

NPIC PROJECT

19087/64 (partial answer)

NSA/P0489/R-64-84 (C)

SECRET NO FOREIGN DISSEM

- 4 -